

CLICK HERE TO PRINT



# MY SUMMARY

## **O YOUR VEHICLE'S HEALTH STATUS**



**ENGINE**: There is a problem that has caused your Check Engine light to turn on; service is required. A recommended solution is provided in this report.

EMISSIONS: Your vehicle could be polluting the environment and will likely FAIL an emissions (smog) test.

## **MY CURE**

Engine / Transmission	Parts Cost	Parts + Labor
Estimated Cost	\$1,963.50	\$2,518.50

# TEST RESULTS SUMMARY Check Engine Light Status = **ON** Ready for Emission Test? = Not Ready Primary (Check Engine) Code = P0740 Available Technical Service Bulletins\* = 117 Secondary Codes = None Available Safety Recalls = 0

## VEHICLE INFORMATION

VIN:	1C4GP54L0YB507122	Transmission Reported:	Automatic
Year:	2000	Owner Name:	John Smith
Make:	Chrysler	Date of Report:	9/17/2009 8:57:03 PM
Model:	Town & Country	Mileage Reported:	90044
Engine:	V6, 3.8L	Test Report ID:	N/A
Trim Level:	LXi	Kiosk Location:	N/A



# MY DIAGNOSIS

CarMD has tested your vehicle's On Board Diagnostic system and has discovered the following conditions during its inspection:

## **CHECK ENGINE LIGHT CODE**

This is the code that caused your "Check Engine" light to turn on and it is the primary code that was used to determine your vehicle's cure

Error Code	P0740
Definition	A/T Torque Converter Clutch - No RPM Drop At Lockup

### Possible Causes:

Internal transmission component fault (Input or Reaction shaft) Internal transmission leakage (valve body leaking or seal rings) Converter clutch valve or clutch timing valve is sticking TCC assembly has failed

**Condition For Setting The Code:** 

Engine started; vehicle driven at over 1750 rpm at 50 mph for 20 seconds, TCC command at 100%, and the PCM detected the engine speed was not within 60 rpm of ISS speed with the TP angle less than 30 degrees. The test must fail 3 times on one trip to set a code.

Technical Service Bulettin (TSB) Available? No

## S STORED DIAGNOSTIC CODES

At times, other codes are set and stored whenever a major problem is detected. These codes are usually related to why your Check Engine light was set. Below are the additional stored codes:

Error Code P0740
Definition A/T Torque Converter Clutch - No RPM Drop At Lockup

### Possible Causes:

Internal transmission component fault (Input or Reaction shaft) Internal transmission leakage (valve body leaking or seal rings) Converter clutch valve or clutch timing valve is sticking TCC assembly has failed

**Condition For Setting The Code:** 

Engine started; vehicle driven at over 1750 rpm at 50 mph for 20 seconds, TCC command at 100%, and the PCM detected the engine speed was not within 60 rpm of ISS speed with the TP angle less than 30 degrees. The test must fail 3 times on one trip to set a code.

Technical Service Bulettin (TSB) Available? No

### MONITOR STATUS INFORMATION

The provided results below also help determine if your vehicle is ready for an Emissions Test (Smog Check). Your vehicle is most likely ready for an inspection if all supported monitors show a COMPLETE status and MIL is OFF.

Monitor Name	Monitor Icon	Status
MIL (Check Engine Light)		ON
Misfire Monitoring	0	Complete
	_	

Fuel System Monitoring	0	Complete
Comprehensive Component Monitoring	<b>©</b>	Complete
Catalyst Monitoring	G	Not complete
Heated Catalyst Monitoring	<b>®</b>	Not Supported
Evaporative System Monitoring	<b>(3)</b>	Not complete
NMHC Monitoring	NM)	Not Supported
NOxAdsorber Monitoring	0	Not Supported
Secondary Air System Monitoring	<b>2</b> A	Not Supported
Oxygen Sensor Monitoring	0	Not complete
Oxygen Sensor Heater Monitoring	OH)	Not complete
EGR System Monitoring	•	Not Supported
Boost Pressure System Monitoring	<b>BP</b>	Not Supported
Exhaust Gas Sensor Monitoring	<b>3</b>	Not Supported
PM Filter Monitoring	0	Not Supported

# **© FREEZE FRAME DATA**

This is your vehicle's operating condition, which was recorded at the time the failure occurred and the **Check Engine** light was set. This information is valuable when performing the fix yourself or if you are having a professional technician perform the repair. The theory is to recreate these parameters to ensure that the problem was indeed corrected.

Parameter Description	Results
DTC for which Freeze Frame was Stored	P0740
Fuel System 1 Status	Open Loop
Fuel System 2 Status	Not Supported
Calculated LOAD Value	0.00 %
Engine Coolant Temp	-40.00 °F
Short Term Fuel Trim - Bank 1	99.22 %
Long Term Fuel Trim - Bank 1	0.00 %
Intake Manifold Absolute Pressure	36.42 inHg
Engine RPM	0.00 rpm
Vehicle Speed Sensor	0.00 mph
Ignition Timing Advance #1 Cylinder	10.00 °
Intake Air Temperature	35.60 °F

Air Flow Rate Mass Air Flow Sensor	0.00 lb/min
Absolute Throttle Position	0.00 %
Commanded Secondary Air Status	Atmosphere / Off
Oxygen Sensor Output Voltage (B1-S1)	1.07 V
Short Term Fuel Trim (B1-S1)	99.22 %
Oxygen Sensor Output Voltage (B1-S2)	0.00 V
Short Term Fuel Trim (B1-S2)	99.22 %
Oxygen Sensor Output Voltage (B1-S3)	0.00 V
Short Term Fuel Trim (B1-S3)	99.22 %

# R

# MY CURE

There are **2** possible fix(es) associated with the diagnostic codes retrieved by **CarMD**. These fixes (or cures) were derived from actual real world repairs taken from qualified ASE Certified Technicians across the U.S. Estimated repair costs are based on parts & labor specific to the actual fix; with parts based on average MSRP and labor based on average National Labor Rates by region.

### **MOST LIKELY FIX** Based on technician feedback, this fix offers the highest probability to resolve the problem. **Replace Transmission Assembly** Recommended Fix: **Parts Required Unit Cost** Quantity **Total Transmission Assembly** \$1,963.50 1 1963.50 **Labor Required Estimated Labor** \$75.00 5.4hrs. \$405.00 Miscellaneous \$150.00 **Estimated Parts Cost:** \$1,963.50 **Estimated Repair Shop Cost (Parts + Labor):** \$2,518.50

### OTHER POSSIBLE FIXES

These fixes were also found by technicians across the country to solve the problem. However, these have a lower probability in repairing the problem. Follow this recommendation when the Most Likely Fix does not resolve the problem.

Recommended Fix:	Replace Transmission Pressure Solenoid Assembly			
Parts Required		Unit Cost	Quantity	Total
Transmission Solenoid Switch Assembly		\$224.40	1	\$224.40

Labor Required			
Estimated Labor	\$75.00	1.1hrs.	\$82.50
Miscellaneous			\$25.00
Estimated Parts Cost:			
Estimated Repair Shop Cost (Parts + Labor):			\$331.90



# STAYING HEALTHY

Keep your vehicle running safely and healthy! CarMD offers the following resources to keep your vehicle in optimum condition. Continue checking this section as we bring you additional information. Tell us what else you would like to see in this section. Send us an email of what you'd like to see in this section

### **TECHNICAL SERVICE & SAFETY RECALL INFORMATION**

Your 2000 Chrysler Town & Country has 117 technical service bulletins and 0 safety recall notices.

TECHNICAL SERVICE BULLETINS		
System Type	No. of TSBs	
Accessories and Fluids	14	
Body	20	
Brake	5	
Electrical	19	
Emission Control	9	
Powertrain	20	
Fuel & Spark	6	
HVAC	4	
Steering & Suspension	16	
Tools & Hardware	3	
Wiper and Washer	1	

SAFETY RECALL NOTICES		
0		

# Thank you for using CarMD.com. Please Drive Safely. www.CarMD.com

This information is designed to guide and empower you in your automotive repair and maintenance decisions. Always consult with a qualified automotive technician before making repairs. Please see detailed Terms and Conditions at any CarMD® kiosk or web site for details.

© 2006-2009 CarMD.com Corp. All rights reserved. Portions copyright © 2005 Cengage Learning. All rights reserved. Used under license. For technical support questions, please call 1.888.MyCarMD (1-888-692-2763) from 6 a.m. to 6 p.m. (Monday to Saturday) Pacific Standard Time.